


G-102A**Strobe Light**

Small Size

**Voltage**

12 Vdc.

Current Max.

55 mA @ 12 Vdc.

50 mA @ 13.8 Vdc.

Flashes

80 / Min.

Install


2 Screw

Color

Red

G-103A**Strobe Light**

Small Size

**Voltage**

12 Vdc.

Current Max.

55 mA @ 12 Vdc.

50 mA @ 13.8 Vdc.

Flashes

80 / Min.

Install


2 Screw

Color

Blue

G-102**Strobe Light**

Large Size

**Voltage**

12 Vdc.

Current Max.

240 mA @ 12 Vdc.

330 mA @ 13.8 Vdc.

Flashes

90 / Min.

Install


2 Screw

Color

Red

G-103**Strobe Light**

Large Size



Yellow (+) 6 Vdc.
White (-) Com.
Red (+) 12 Vdc.

Voltage

12 or 6 Vdc.

Current Max.

240 mA @ 12 Vdc.

330 mA @ 13.8 Vdc.

Flashes

90 / Min.

Install

2 Screw

Color

Blue