

FTTH PROFESSIONAL TOOL W/POWER METER



STANDARD PACKAGE

1. Carrying bag
2. Power meter
3. Kevlar scissors, new style
4. F.O. visual fault locator
5. Manual pro cleaver
6. FTTH drop fiber stripper, new style
7. 3 hole fiber stripper, new style
8. F.O. Stripper and length bar
9. F.O. clean stick 2.5 mm.
10. Alcohol's bottles



Part Number	Description
UFH3020	FTTH PROFESSIONAL TOOL w/Power meter

FIBER OPTIC TOOL KIT

KIT CONTENTS

1. UF-2821 WIPE PAPER
2. UF-2823 CLEANSER LIQUID
3. UF-2826 A/B FAST EPOXY GLUE (COMPLETE BOND 30 MINUTES)
4. UF-2825 EPOXY SYRINGE
5. UF-2830 (0.3mm - WHITE COLOR) POLISH FILM
6. UF-2831 (1.0mm - GREEN COLOR) POLISH FILM
7. UF-2835 (5.0mm - BROWN COLOR) POLISH FILM
8. UF-2803 FIBER COATING 250-900mm STRIPPER
9. UF-2804 KEVLAR SCISSORS
10. UF-2806 CRIMP TOOL (ST, SC, FC)
11. UF-2808 CARBIDE SCRIBE
12. UF-2810 ST POLISH DISC
13. UF-2812 SC POLISH DISC
14. UF-2814 RUBBER WORKING PAD
15. UF-2816 GLASSES WORKING PAD
16. UF-2825 SYRINGE
17. EPOXY MIXER
18. EPOXY MIXER PAD



Part Number	Description	Box Dimension L x W x H(mm)
UF-2840	Fiber Optic PROFESSIONAL TERMINATE SET (No Optical Scope)	297 x 197 x 60

CLEAVER AUTO / MANUAL, F.O. MICROSCOPE, F.O. VISUAL FAULT LOCATOR



UF-2844A



UF-2851



UF-2883

Part Number	Description	Battery
UF-2844	F.O. Auto Pro Cleaver	-
UF-2845	F.O. Manual Pro Cleaver	-
UF-2851	F.O. Microscope 400X w/ST, SC, FC & LC Adapter	2A x 3
UF-2883	F.O. Visual Fault Locator (Heavy Duty) > 10 mw for ST, SC, FC (7 Km.)	2A x 2
UF-2884	F.O. Visual Fault Locator (Heavy Duty) > 10 mw for LC (7 Km.)	2A x 2
UF-2885	F.O. Identifier	2A x 2